SITE CONDITION ASSESSMENT

LINDA VISTA PROPERTY

Area	5.00 Acres 217,783 SF
Parking Spaces	None
Walk Score	12 Car-dependent

- Mt Lion Bus Stop
- Communications
- Gas Service
- Power Service
- Sewer Service
- Water Service
- Well
- Fire Hydrant
- Aerial Power Line
- Irrigation Ditch
- Water Mains
- Sewer Manholes
- Sanitary Sewer
- Trails
- Bike Lanes
- MCPS Property
- Zoning
- Parcels

0 50 100 200 Feet

WGM GROUP

1111 E. Broadway | Missoula, MT 59802
www.wgmgroup.com

PROJECT: 120508
FILE: S29 of 32_LVP
PATH: W:\Projects\120508\GIS\MXD\S29_Linda Vista Property
BY: KD
REVIEWED: BC
DATE: 8/13/2013

Disclaimer: This map is neither a legally recorded map nor a survey and is not intended to be used as such. WGM Group does not guarantee the accuracy, current status, or completeness of the material contained herein and is not responsible for any misuse or misrepresentation of this information or its derivatives. This map is a graphic representation and is to be used for general planning purposes only.